

German Intensity Standard VD13882/3940 Scale

O Not detectable

1 Very weak

2 Weak

3 Distinct

4 Strong

5 Very strong

6 Extremely strong

Assessment Area

Harwood Rise (on elbow)

Capill Corner (cul-de-sac)

Noreat Place

< less than

SMRC RRRC - Field Based Ambient Odour Intensity Assessments June 2021 Date JUN Wind E, ESE **Street Location** I.D. **Average** Cnr. Dundee Street & Beasley Road 1 0 Beasley Road (middle) 2 0 Cnr. Beasley Road & Hollingsworth Way 3 0 Hollingsworth Way (middle) 4 0 Cnr. Hollingsworth Way & Roe Hwy Footpath 5 0 Roe Highway Footpath (middle) 6 0 Cnr. Roe Hwy & Dundee Street 7 0 Dundee Street (middle) 8 0 Cluelow Rise (cul-de-sac) 9 0

10

11

12

0

0

0