



EAQ Consulting

**German Intensity Standard
VD13882/3940 Scale**

- 0 Not detectable
- 1 Very weak
- 2 Weak
- 3 Distinct
- 4 Strong
- 5 Very strong
- 6 Extremely strong
- < less than

Assessment Area 1

SMRC RRRC - Field Based Ambient Odour Intensity Assessments		
May 2021		
	Date	MAY
	Wind	E, ESE
Street Location	I.D.	Average
Cnr. Dundee Street & Beasley Road	1	0
Beasley Road (middle)	2	0
Cnr. Beasley Road & Hollingsworth Way	3	0
Hollingsworth Way (middle)	4	0
Cnr. Hollingsworth Way & Roe Hwy Footpath	5	0
Roe Highway Footpath (middle)	6	0
Cnr. Roe Hwy & Dundee Street	7	0
Dundee Street (middle)	8	0
Cluelow Rise (cul-de-sac)	9	0
Harwood Rise (on elbow)	10	0
Capill Corner (cul-de-sac)	11	0
Noreat Place	12	0