

German Intensity Standard VD13882/3940 Scale

Not detectable

1 Very weak

2 Weak

3 Distinct

4 Strong
5 Very strong

6 Extremely strong

< less than

RRG – Canning Vale Centre – Field Based Ambient Odour Intensity Assessments

JUNE 2024

	Date	JUN
	Wind	E, SE
Street Location	I.D.	Average
Cnr. Hollingsworth Way & Roe Hwy Footpath	5	0
Roe Highway Footpath (middle)	6	0
Cnr. Roe Hwy & Dundee Street	7	0
Dundee Street (middle)	8	0
Cluelow Rise (cul-de-sac)	9	0
Harwood Rise (on elbow)	10	0
Capill Corner (cul-de-sac)	11	0
	Cnr. Hollingsworth Way & Roe Hwy Footpath Roe Highway Footpath (middle) Cnr. Roe Hwy & Dundee Street Dundee Street (middle) Cluelow Rise (cul-de-sac) Harwood Rise (on elbow)	Street Location I.D.

Assessment Area 3

Cnr. Merrifield & Roe Hwy	1	0
Merrifield (middle)	2	0
Cnr. Beasley & Merrifield	3	0
Beasley	4	0